## 0288

: | | |

	BLUE 0V	)	300V	ORANGE(1)	0.11A
		)	( 0V	GREY (1)	U.IIA
(1)	WHITE 110V	)	( 300V	ORANGE (2)	
		)	300V	ORANGE (2)	0 117
	RED 120V	)	( 0V	GREY (2)	0.11A
	BLACK 0V	)	( 300V	ORANGE (2)	
(2)		):	   (	YELLOW (1)	1.1A
	WHITE 110V	)	( 6.3V	YELLOW (1)	
		) :	   (	YELLOW (2)	1 1 2
	BROWN 120V	)	( 6.3V	YELLOW (2)	1.1A
		:	   (	PINK	6.7
		:	(  (7.5V	PINK	6A
For		ED & BLACK.	 ELECTROSTATIC : Use BLUE & BRO TES separately	WN	

For 120V: Join BLUE & BLACK OV and join RED & BROWN 120V. (Isolate both WHITES)

For 110V: Join BLUE & BLACK OV and join both WHITES 110V. (Isolate RED & Isolate BROWN)

\* FOR PRIMARY WINDING WITH SOLID CORE WIRE AND SLEEVING If the WHITE leads are cut short please ensure the TWO wires inside the sleeving are joined together in BOTH cases.

The solid wire inside the sleeving is coated with polyurethane and needs to be stripped away and tinned if the leads are shortened. For secondary windings with solid core leads please follow the same process.

FOR FLEXIBLE LEADS PRIMARY AND SECONDARY: Just cut short and isolate any spare connections

NOTE: A certain amount of mechanical hum is prevalent in mains transformers and can be amplified when bolting to your metal work. Therefore you may find a small rubber gasket or similar material is worth fitting to quieten this hum to its' minimum, but please ensure the frame is grounded to the supply safety earth.