
Type No. 7702 to specification discussed.



Turns ratio 5.51+5.51: 1+1.

For further technical details or advice please call Brian Sowter on 01962 620135.

Please find replacement plates and lids as requested. Note the plates are made of Stainless Steel and not Aluminium as we first suggested. The engineering company who made them, advised us that in their opinion the small amount of thread would not have held in Aluminium, hence the change.

If you desolder the can and the give the lid a sharp blow (it doesn't have to be particularly hard) using a screwdriver and hammer, it should come apart fairly easily the new lid can then be Araldited on and re-soldered.

If you are not happy doing this then just send it back and we will process and return immediately.