


8336



JOIN PRIMARIES IN SERIES FOR 5000 OHMS USE (BROWN/GREEN BECOMES CENTRE-TAP)

JOIN SECONDARIES IN SERIES FOR 5000 OHMS USE (WHITE/GREY BECOMES CENTRE-TAP)