

0632o

BLACK	0V	_____) : (_____	0V ORANGE	
) : (_____		0.64A
) : (_____	398V ORANGE	
) : (_____		
) : (_____	0V GREY	
) : (_____		0.16A
) : (_____	160V GREY	
) : (_____		
) : (_____	0V PINK	0.16A
) : (_____	210V PINK	
) : (_____		
) : (_____	0V YELLOW (1)	
) : (_____		4A
) : (_____	6.3V YELLOW (1)	
BROWN	240V	_____) : (_____		

			: (_____	0V YELLOW (2)	
			_____		4A
			: (_____	6.3V YELLOW (2)	

			: (_____	0V YELLOW (3)	
			: (_____		2A
			_____	6.3V YELLOW (3)	
			:		
YELLOW/GREEN		_____		ELECTROSTATIC SCREEN	

* FOR PRIMARY WINDING WITH SOLID CORE WIRE AND SLEEVING

The solid wire inside the sleeving is coated with polyurethane and needs to be stripped away and tinned if the leads are shortened.

FOR FLEXIBLE LEADS PRIMARY -

just cut short and isolate (INDIVIDUALLY) any spare connections

Note: A certain amount of mechanical hum is prevalent in mains transformers and can be amplified when bolting to your metal work. Therefore you may find a small rubber gasket or similar material is worth fitting to quieten this hum to its' minimum, but please ensure the frame is grounded to the supply safety earth.