

Hi Z primary to secondary = Turns Ratio 1:1

Low Z (a) + Low Z (b) connected in parallel = Turns Ratio 1:20

Low Z (a) + Low Z (b) connected in series = Turns Ratio 1:10