


8871



Primary Windings:

Series connected for 600 ohms use.

Parallel connected for 150 ohms use.